

B Thermal Inspection Report

G



B Electric Pty.Ltd

Electrical Contractors Licence 5457 A.C.N 010 290 016 A.B.N 24 010 290 016

P.O.Box 2030 Fortitude Valley Qld 4006 Ph:3854 1717 Fax:3252 7728

Email: robert.shaw@bgbelectric.com

Client and Site Contact	100 Smith St, Brisbane Barry Brown
Location of Equipment	Level 1 Plant Room Mechanical Services Switchboard
Equipment	Pump 1 White Phase Fuse
Time of Image	10.30 AM
Date of Image	3/3/2017
Report No.	2
Thermographer	Mark Blanch



Hot Spot Temperature	77.2°C
Reference Temperature	44.9°C
Thermographers Comments	Heat signature indicates loose internal fuse contacts.
Repair Date / Comments	Replace fuse base and fuse.
Next Survey Due	March 2018